

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
6: Okoboji-----	95	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Hard to compact Too clayey	1.00 1.00 0.50
27: Terril-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
29: Clarion-----	50	Not limited		Not limited		Not limited	
Nicollet-----	30	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
41B: Sparta-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
41C: Sparta-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
55: Nicollet-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
62D3: Storden-----	90	Somewhat limited Slope	0.16	Somewhat limited Slope	0.16	Somewhat limited Slope	0.16
62E3: Storden-----	90	Very limited Slope	1.00	Very limited Slope	1.00	Very limited Slope	1.00
73C: Salida-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage Gravel content	1.00 1.00 1.00

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
73D: Salida-----	95	Very limited Seepage Too Sandy Slope	 1.00 1.00 0.63	Very limited Seepage Slope	 1.00 0.63	Very limited Too Sandy Seepage Gravel content Slope	 1.00 1.00 1.00 0.63
73F: Salida-----	95	Very limited Seepage Too Sandy Slope	 1.00 1.00 1.00	Very limited Seepage Slope	 1.00 1.00	Very limited Too Sandy Seepage Slope Gravel content	 1.00 1.00 1.00 1.00
83: Kenyon-----	95	Very limited Depth to saturated zone	 1.00	Very limited Depth to saturated zone	 1.00	Not limited	
83B: Kenyon-----	95	Very limited Depth to saturated zone	 1.00	Very limited Depth to saturated zone	 1.00	Not limited	
83C2: Kenyon-----	95	Very limited Depth to saturated zone	 1.00	Very limited Depth to saturated zone	 1.00	Not limited	
84: Clyde-----	95	Very limited Depth to saturated zone	 1.00	Very limited Depth to saturated zone Seepage	 1.00 1.00	Very limited Depth to saturated zone Seepage	 1.00 0.50
95: Harps-----	95	Very limited Depth to saturated zone	 1.00	Very limited Depth to saturated zone	 1.00	Very limited Depth to saturated zone	 1.00
107: Webster-----	95	Very limited Depth to saturated zone	 1.00	Very limited Depth to saturated zone	 1.00	Very limited Depth to saturated zone	 1.00

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
135: Coland-----	95	Very limited Flooding	1.00	Very limited Flooding	1.00	Very limited Depth to saturated zone	1.00
		Depth to saturated zone	1.00	Depth to saturated zone	1.00	Too clayey	0.50
		Seepage	1.00				
		Too clayey	0.50				
138: Clarion-----	100	Not limited		Not limited		Not limited	
138B: Clarion-----	90	Not limited		Not limited		Not limited	
138C2: Clarion-----	85	Not limited		Not limited		Not limited	
151: Marshan-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
		Seepage	1.00			Too Sandy	1.00
		Too Sandy	1.00			Seepage	1.00
152: Marshan-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
		Seepage	1.00			Too Sandy	1.00
		Too Sandy	1.00			Seepage	1.00
153: Marshan-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
		Seepage	1.00			Too Sandy	1.00
		Too Sandy	1.00			Seepage	1.00
169B: Clarion-----	95	Not limited		Not limited		Not limited	
171: Bassett-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
171B: Basset-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
173: Hoopeston-----	95	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Somewhat limited Depth to saturated zone Seepage	0.86 0.50
174: Bolan-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
174B: Bolan-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
175: Dickinson-----	90	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
175B: Dickinson-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
175C: Dickinson-----	100	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
177: Saude-----	100	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
177B: Saude-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
177C: Saude-----	100	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
178: Waukee-----	95	Very limited Seepage	1.00	Not limited		Not limited	
178B: Waukee-----	95	Very limited Seepage	1.00	Not limited		Not limited	
184: Klinger-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.09
188: Kensett-----	95	Very limited Depth to saturated zone Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Depth to saturated zone	1.00 0.09
198: Floyd-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Somewhat limited Depth to saturated zone	0.09
213: Rockton-----	100	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock	1.00
213B: Rockton-----	100	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock	1.00
214: Rockton-----	95	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock	1.00

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
214B: Rockton-----	95	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock Seepage	1.00 1.00	Very limited Depth to bedrock	1.00
221: Palms-----	95	Very limited Depth to saturated zone Content of organic matter	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Content of organic matter Seepage	1.00 1.00 0.16
221B: Palms-----	90	Very limited Depth to saturated zone Content of organic matter	1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Content of organic matter Seepage	1.00 1.00 0.16
225: Lawler-----	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00 1.00 0.09
226: Lawler-----	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Too Sandy Seepage Depth to saturated zone	1.00 1.00 0.09
235: Coland-----	50	Very limited Flooding Depth to saturated zone Seepage Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Turlin-----	30	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 1.00	Very limited Flooding Depth to saturated zone	1.00 1.00	Not limited	
236B: Lester-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
236B2: Lester-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
236C: Lester-----	95	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
236C2: Lester-----	90	Somewhat limited Too clayey	0.50	Not limited		Somewhat limited Too clayey	0.50
236D2: Lester-----	90	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Somewhat limited Slope Too clayey	0.63 0.50
236E2: Lester-----	95	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
236F: Lester-----	100	Very limited Slope Too clayey	1.00 0.50	Very limited Slope	1.00	Very limited Slope Too clayey	1.00 0.50
274: Rolfe-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
284: Flagler-----	90	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
284B: Flagler-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Seepage Too Sandy	1.00 0.50
321: Boots-----	100	Very limited Depth to saturated zone Content of organic matter Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Content of organic matter Seepage	1.00 1.00 0.21
325: Le Sueur-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.09
329: Webster-----	50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
Nicollet-----	30	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
335: Harcot-----	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00
354: Marsh-----	100	Not rated		Not rated		Not rated	
377: Dinsdale-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
377B: Dinsdale-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
382: Maxfield-----	100	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
399: Readlyn-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.09
407: Schley-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.86
471: Oran-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.09
507: Canisteo-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
558: Talcot-----	100	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00
559: Talcot-----	100	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Too Sandy Seepage	1.00 1.00 1.00

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
583: Minnetonka-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Too clayey	1.00 1.00
621: Houghton-----	95	Very limited Depth to saturated zone Content of organic matter Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Depth to saturated zone Content of organic matter Seepage	1.00 1.00 0.16
638B2: Clarion-----	50	Not limited		Not limited		Not limited	
Storden-----	30	Not limited		Not limited		Not limited	
638C2: Clarion-----	50	Not limited		Not limited		Not limited	
Storden-----	30	Not limited		Not limited		Not limited	
651: Faxon-----	100	Very limited Depth to saturated zone Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to saturated zone Depth to bedrock Seepage	1.00 1.00 1.00	Very limited Depth to bedrock Depth to saturated zone	1.00 1.00
695: Tilfer-----	100	Very limited Flooding Depth to saturated zone Depth to bedrock Seepage	1.00 1.00 1.00 1.00	Very limited Flooding Depth to saturated zone Depth to bedrock Seepage	1.00 1.00 1.00 1.00	Very limited Depth to bedrock Depth to saturated zone	1.00 1.00
706: Donnan Variant-----	85	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Too clayey Hard to compact Depth to saturated zone	1.00 1.00 0.47

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
706B: Donnan Variant-----	85	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Too clayey Hard to compact Depth to saturated zone	1.00 1.00 0.47
725: Hayfield-----	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Too Sandy Seepage	1.00 1.00
726: Hayfield-----	95	Very limited Depth to saturated zone Seepage Too Sandy	1.00 1.00 1.00	Very limited Depth to saturated zone Seepage	1.00 1.00	Very limited Too Sandy Seepage	1.00 1.00
733: Calco-----	100	Very limited Flooding Depth to saturated zone Seepage Too clayey	1.00 1.00 1.00 0.50	Very limited Flooding Depth to saturated zone	1.00 1.00	Very limited Depth to saturated zone Too clayey	1.00 0.50
755: Nicollet-----	90	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Not limited	
761: Franklin-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Somewhat limited Depth to saturated zone	0.09
777: Wapsie-----	100	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
777B: Wapsie-----	95	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
777C2: Wapsie-----	100	Very limited Seepage Too Sandy	1.00 1.00	Very limited Seepage	1.00	Very limited Too Sandy Seepage	1.00 1.00
782: Donnan-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Too clayey Hard to compact Depth to saturated zone	1.00 1.00 0.47
782B: Donnan-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Too clayey Hard to compact Depth to saturated zone	1.00 1.00 0.47
782C2: Donnan-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Too clayey Hard to compact Depth to saturated zone	1.00 1.00 0.47
836B: Kilkenny-----	95	Somewhat limited Too clayey	0.50	Not limited		Very limited Hard to compact Too clayey	1.00 0.50
836B2: Kilkenny-----	95	Somewhat limited Too clayey	0.50	Not limited		Very limited Hard to compact Too clayey	1.00 0.50

Sanitary Facilities - Part 2.

Worth County, Iowa

Map symbol and soil name	Pct. of map unit	Trench sanitary landfill		Area sanitary landfill		Daily cover for landfill	
		Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
836C2: Kilkenny-----	95	Somewhat limited Too clayey	0.50	Not limited		Very limited Hard to compact Too clayey	1.00 0.50
836D2: Kilkenny-----	95	Somewhat limited Slope Too clayey	0.63 0.50	Somewhat limited Slope	0.63	Very limited Hard to compact Slope Too clayey	1.00 0.63 0.50
855: Shorewood-----	95	Very limited Depth to saturated zone Too clayey	1.00 1.00	Very limited Depth to saturated zone	1.00	Very limited Too clayey Hard to compact	1.00 1.00
956: Okoboji-----	50	Very limited Depth to saturated zone Too clayey	1.00 0.50	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone Hard to compact Too clayey	1.00 1.00 0.50
Harps-----	30	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
977: Richwood-----	100	Very limited Seepage	1.00	Not limited		Not limited	
C315: Mixed Alluvial Land-	90	Not rated		Not rated		Not rated	
T506: Wacousta-----	95	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00	Very limited Depth to saturated zone	1.00
W: Water-----	100	Not rated		Not rated		Not rated	